HERITAGE - WTI, INC.

1250 St. George Street East Liverpool, OH 43920

Telephone: (330) 385-7336 Fax: (330) 386-2167

TO: Susan Shew Czyk
COMPANY: Oregon DEQ
FAX: (503) 373-7944
FROM: [arrie Paringe [EHS Manager]
DATE: 2/16
RE: Requested Documents
PAGES: 14 GNGY YIPING COVER SHEET)
(INCLUDING COVER SHEET)
PLEASE NOTIFY US IF YOU DO NOT RECEIVE ALL PAGES
CC:
CC: Jess Brown COMMENTS:
COMMENTS:
DOT: soudside for importions.
ZR=drums
had been
ghald transportation
- 433 - dangerous when wet -
1 Distinguished and
Mote: dust friction can course esp.
A. Sesled Josephacked

							IAI								
?^ + =	ıa ed	int or type. (Form	designed for US	se on elila (12	-pitch) typewi	iter.)					74, Manifest Ti	Form	Approved.	OMB No. 2	050-0039 1
reas T	HWR HWR	FORM HAZARDO	US 1, Genera	for ID Number			2. Page 1 of	Į.	gency Response	Р∱юл≉		116		1 VE	S
,	W	aste manifes	COR	0 0 5 0 5	5584	6 '		(877)	818-0087	d different tha			131	<u> </u>	
11	5. €	ateralora Name are	Mailing Address	WAHLE	IANG - NO	RTH		WAH	CHANG - N CIX 460	ÖRTH	n mašing address				
				PO BOX	450 YAN 60D , OR 973	LY		0000	OLD SALE	M ROAD	NE)				
П	laves	eralor's Phone 541	812-7003	ALBANY	, OR 973	210460	9 - 0	ALBA	VY, OR 97	327U46U			4 		
11	Gent B. Tr	erator's Phone." ansporter i Compa	ry Name					la .		•	U.S. EMIDN		п з э	6 6 9	- 1
		VANNAHTRA		447		_		_		~~~	U.S. EPAID N		4.00,000		
	7.7	ransporter 2 Compa	ny Nam¢	- 1,000 to 1,000 to 1					1		1				- 1
	ļ			Lora			ny Co*	American			U.S. EPAID N	omber			
3	8.0	esignaled Facility N	三川名 別い ひばんか	ATISSHI ^{CO}	MALCEON	NC; RGE STRE	ET						8		
١											IOHD	α Α	n s 1	3 5 4	(1 -
	Fac	atys Phonec 330	385-7336	EASIL	IVERPOO	L; OH 439	?O	-				10 1000000000	7		- 1
	98	66. U.S. DOT-	Jasznobon (includ	And Proper Ship	ping Name, Haz	rand Class, 10 No	Uper,	-7	10. Conta	ners Type	11. Total Quantity	12 Unit WLVAL	13,	Wසෝග Code	ន
	HI	and Packing G			MATIONALII	~			1 11/4	172			NONE		
湿	X	1.03178, F	LAMMABL JM, HAFNII	E SOUD, 1 JM), 4.1, 1)	NORGANI İ	∪, 1).0.3 ₁₁			040	DM	43,180	P			
녆		(E) (OO)									1-710-				
GENERATOR	<u> </u>	2.			*******		4			1		Î	<u> </u>		
4	3											•	<u> </u>		
1									 -	1		1			
11	Г	3,							ì					 	
	1								1	1				_	
11	l	4.			 									es A company	
11		25.7"								1					
			W1900 Al 4	27.00					0.5504	777 14642	#442 ANNIT	027964	_ <u></u> 1		<u> </u>
1	1 7	र्. इंग्वर्टा <u>स्थित</u>	Instructions and A	Motel length bit	sum ER 5	Service Con	tracted by V	E\$16 -	}- 1) ERG;	N.A. Vial	7.7.7.7.7.7.7	n.	10		
1		***				•				Viol	ia te	71 .	70011	5-1	
1							-300		·	-		/_	1010	35/2	Noned
1	1	5. GENERATOR'S	HOFFEROR'S CT	KITECATION	Thereby declar	क सम्बद्धि के स्थापन कर किया क	ts of this coresignar part according to	ont are ful collected	y and accurately nternational and r	රුදුන්ට පිරිදුන් ප්රදේශයේ පුරුණා	we by ma proper:	er ji cabou asbbaid ta	Epitalistof Box	g I sut the bu	interly
Ì	11	median and inte	e wilder an uni. S	no ere u oviesi	PATE III INTERIOR (Whomps for a car	P								
	1	i certify that the	ilezhnidari etzevi	on statement ox	nsted in 40 CF	R 26227(3) (41)	a allached EPAAC em a jerge quanth	Signally		<i>-171 '</i>				nontr D	sy Year'
1	G	Servicia Politico de	Princed types no	PANK	Han	AKTON!		. //	adull.	الاِر				12/6	2_1//_
1	<u>+ </u>	6. International Shi	menis /		SE	ur teszé	☐ Export 1	Un U.A.	Parto	entylesit _					
	⊢ −	Transporter algradu		∭lmport το U	,es,				Dale k	aving U.S.			-		
ľ		Tr. Transporter Acts	ow/adgmodiof Re	व्यक्तिकारी हैं। (वृह्यक	\$			Signalon			/			Month D	sy Yes
		itarisporter 1 Printe	, ,	-12	572	En .			19	At	A CONTRACTOR OF THE PARTY OF TH			12/2	0//
1	찚	SAXO Transporter 2 Printer		- الراري				Signatur	9				1	Month ₽ 1	ыу Үсэ∤ І
-	TRANSPORT	Here Solved # 4 fance													
١		18, Discrepency												∐i*di!	
1		(Ba. Discrepancy li	dication Space	Oxens	y		Type		Residua		Partial	Rejection			(delective)
	Ш								. Manuara Refer	ence Number					
20	,	18b. Allemate Faci	iv inc Generalor)	-	4.000				25		KABLEN	10 Number			
15	FACILITY	fon-Weltard no	·					•			1				
	4	Facility's Phone	•		VALE 50 40 9			-	71.710.00					Month	Day Yea
		18c. Signalans of A	Jemala Facility (y Generator)										Ī	
93	3					- Con harmonia de la constanta	vesefa knaiment	fsvæl æ	d recycleng syste	ms)	***************************************		44		
	DESIG	19. Hazardous Wa	ste Report Manag	covery Method	Codes (i.e., cod 2	ES (OL LISTSHOOPE	Muzer necessions	3.			4.		1		
	ă	1.	1-1-121	40		\		1	and a	1	7 1.	,	<u> </u>		- V
		20. Designated Fa	edity Overhal or Or	eraco: Carlina	हिंद्रा की सक्दांको व	lem zvojiczai)	भूकांट का ध्वास्त्र हो। ह	स्ट्राह्म का स्ट्राह्म	exceptes तिस्रो	M Item #	1			Month	Day Yso
	11	Printed/Typed Na	ner -	1 1				නිඉහර	"	-	and the	gai.	ممس	1/2/	12 1
		Lingson Librar Lid	10 E (20 100)	1 1 177	. 10	471 -	1.1	1	_				200		
	Ų_	A Form 8700-22 (le	met			40		SIGNATE:	FACILY	TY TO DES	TINATI	ON STA	TE (IF B	EQUIRE



Wastestream 92796 - 1

GENERATOR INFORMATION

Name:

WAH CHANG

Address (site):

*1600 OLD SALEM ROAD NE ALBANY, OR 97321-0460 UNITED STATES

Address (mail):

PAT MACAULEY P O BOX 460 ALBANY, OR 97321-0460 UNITED STATES

US EPA ID:

ORD050955848

State ID:

Regulatory Status:

LARGE QUANTITY

Technical Contact:

FRANK HAMILTON

Phone:

(541)926-4211

Short Name:

WCAO

WASTESTREAM INFORMATION - GENERAL

Common Name:

NON FERROUS METAL FINES & METAL RESIDUE

Waste Class:

071 - WATER-REACTIVE, FLAMMABLE METAL POWDERS

Generating Process:

MACHINE CONDITIONING

EPA Source Code:

GOS - METAL FORMING AND TREATMENT (PICKLING, HEAT TRE...

EPA Form Code:

W307-METAL SCALE, FILINGS AND SCRAP (INCL METAL DRUMS)

Physical State @ 70F:

SEMI-SOLID

Odor:

Color:

Density:

LB/GAL

Estimated

200000 LBS

Annual Volume:

Conditional Approval?: N

MANAGEMENT SYSTEM ASSIGNMENTS

TSD# Product Code - Desc

Put Away Area

Process System - Desc

FRONT WALL

Cont Type

15119

15119 HO74 SOLMIX NON MTL DRUM

8073 SOLMIX METAL DRUM A

GENERAL STORAGE GENERAL STORAGE

FRONT WALL 1251

1251

DF, DM DF, DM

EPA HAZARD CODES

None specified

STATE HAZARD CODES

None Specified



Wastestream 92796 - 1

SAFETY INFORMATION

HMIS Information

Description

HEALTH

1-SLIGHT HAZARD

FLAMMABLE

2@ - MODERATE HAZARD-WATER REACTIVE

REACTIVE

2 - MODERATE HAZARD

PPE

F2 - DUST RESP-NEOPRENE

* = Carcinogen @ = Water Reactive

COMMENTS

Type Text

on hold pending investigation

PE APRON

PI

PPE-F2

THIS MATERIAL NEEDS PACKAGED IN 400 LB CHARGES WETTED WITH OIL.

IN-INTERNAL

PE-PROTECTIVE EQUIPMENT

PI-PROCESS INSTRUCTION

TRANSPORTATION INFORMATION

Shipping Description:

RQ,UN3178,FLAMMABLE SOLID, INORGANIC, N.O.S.,4.1,PGIII,(HAFNIUM,

ZIRCONIUM), ERG#133

Label Codes:

4:1-FLAMMABLE SOLID

COMMENTS

Type Text

NO SAMPLE REQD LM

LM - LABEL-MESSAGE

SURVEY RESPONSES

PHYSICAL AND CHEMICAL PROPERTIES.

			1992
Question	Reply	Question	Reply
Flash Point	140 to <200	Boiling Point	>100
	3000	BYU/LB, range, high value	8000
BTU/LB, range, low value		PH, range, high value	12
PH, range, low value	3		Ю
Is the waste pumpable?	ИО	Will heat improve the flow?	NO
Is this a dust hazerd?	ИQ		

ADDITIONAL HAZARDS.

Question	Reply NO	Question Asbestos	<u>Reply</u> NO
Air Reactive	ИО	Gas	NO
Diovina Eurana provocusors	NO	Explosive	МО



Wastestream 92796 - 1

ADDITIONAL HAZARDS.

Reply Question Reply Question NO Lab Pack NO Infectious Agents NO Pyrophoric NO Oxidizer NO Shock Sensitive NO Radioactiva

YES Water Reactive

ADDITIONAL REGULATORY INFORMATION.

Reply Question Reply Question Subject to Benzene NESHAP controls (40CFR61.340-358) ? Not Applicable NO

PCBs ? (If Yes, specify range)

YES

WI

Reply Question Reply Question

Miscellaneous Special Waste



Wastestream 92796 - 1

CHEMICAL CONSTITUENTS

Using specific chemical names, list all constituents present in the wastestream. Attach available analyses or Material Safety Data Sheets (MSDSs). Total composition must equal or exceed 100%.

TYPE - GENERATOR

Constituents METAL RESIDUE/METAL FINES	CONTAINING:	Range 94 - 99	Result	<u>Units</u> PERCENT	CAS#	EHS ID#	<u>Date</u> 11-JAN-01
CÁLLING ĢIĘ.		1-4 10-25	8•	PERCENT PERCÈNT	7440-58-6	•	10-MAL-11 10-MAL-11
HAFNIUM NIOBIUM	•	10-25		PERCENT	a monte and a		11-JAN-01 11-JAN-01
TITANIUM WATER	· · · · · · · · · · · · · · · · · · ·	10 - 25 0 - 2		PERCENT PERCENT	7440-32-6	7	10-MAL-11
ZIRCONIÚM	₹•	45 - 65		PERCENT	7440-67-7		11-JAN-01

EHS - Extremely Hazardous Substance CAS - Chemical Abstracts Service



Wastestream 92796 - 1

CONSTITUENT RANGES

Constituents Result CAS# Range Units EHS? ID# Date ASH % -50 50 PERCENT NA 19-OCT-99 **HEAT VALUE** - 8000 8000 **BTU/LIS** NÀ 19-OCT-99

EHS - Extremely Hazardous Substance CAS - Chemical Abstracts Service



Heritage-WTI, Inc. Incident Report

2011.1539

To be completed by the employee and supervisor before the end of the shift.

beinte the eur oi me a		Lancaura A American		And a contract of the contract				
l. Incident Inform	ation:							
Date:	12/17/2011	Time:	13:00					
National Control of the Control of t	Fire/Explosion							
Location:	Container Processing	Splitting Area						
Investigator(s):			Winde Hamrick Christine Shorokey Carrie Beringer Randy Sadler Curt Moffett Keith Moyer Steve Olesky					
Investigators - Man	ager:		Russ Henry					
Investigators - Safe	ty Technician:		Jill Auteri					
Investigators - Emp	oloyee:		Russ Henry Jim Brinker	ATTOCKMENT				
Investigators - Othe	:हाड:		Mike Nicholson Steve Lorah John Peterka					
Attachments:			A Spatial way					
II. Employee Info	rmation:							
Name:	Tom Bailey			T				
Department:	BOP	Job Title	: Safety Service	i écuuiciau				
Supervisor (GM) on Daty:	Russ Henry	Overtime	e: Yes	No				
	A AND THE STATE OF	If other than VRA	All March					
Company Name:		Annual Control of the	Annual An	A CONTRACTOR OF THE PARTY OF TH				
Company Address:	-		Multiple and the second					
Company Phone:	A ADMINISTRAÇÃO DE LA CONTRACTOR Y	Was Company - Notified?:	Yes	No				
III. Incident Scen	e Information:			— g				
Specific Location:	BOP, floor behin	d splitting platformate	altar					
PSM Location:	Yes	N o						
Describe How the Incident Occured: While splitting profile 92796-1, a violent exothermic reaction initiated a fire that injured two employees. A responder ireceived minor burns during rescue.								
Type of Machinery/ Dalmac, Hand Tools	Equipment/Materials/\	Waste Involved:						

92796-1 Waste Stream Profile: Confainer Number: Machinery / Equipment Placed: Out of Service Repairs Required

JAMS Work Order Number(s):

Protecto Wire Dalmao Vapor Recovery Snorkle Split Altar Computer Web Styles Safety Shower/Eye Wash Fork Truck Fire Supression System Lighting

IV. Events Causing the Incident:

Describe the events and conditions that contributed to the incident. Include information on the worker, machinery and equipment, environment and management.

Currently under investigation.

V. Corrective Actions:

Identify the factors listed above that can be corrected to prevent a reoccurrence of this type of accident. Indicate the person responsible for making the change and project a target date for completion of the task.

** Initial - Corrective Actions:

Stopped all waste processing and responded to the incident. Resumed limited operations Saturday evening. Re-evaluated processing restrictions on Monday.

Delayed waste receipts Monday.

Transferring all drums of profile 92796-1 to a van for storage in 90 day north.

Caution taped incident area for limited access and further investigation.

24 hour monitoring of incident area and drums on splitting floor via camera in control room until fire supression is repaired and automated.

Cancelled all activity on Wah Chang waste streams.

Removed drums in queing lanes and staged them in the caution taped incident area.

Collected debris and other items that were most likely involved in the incident, bagged it, and set it under lock and key for evaluation at a later date.

** Long Term - Corrective Actions:

Yet to be determined.

CPAR Genera	ted:	Yes		No					
Responsible P Target Comple Method of veri		ective Acti	ion,		12:00:00 AM				
Verification Da	ite:				12:00:00 AM				
V. Incident R	eport Prepar	ed by:							
Name:	Keith Moyer	8.5	Title:	Field Services Manager					
Signature:	Keith Moyer		Date:	12/19/2011 1:20:55 PM	A A THE STREET AND A STREET AND				
VI. Summary	14			A A arm determine to the control of	,				
Include comments that would promote a safe workplace environment and reduce an accidents potential in the future based on review of the events causing the incident and implementation of Corrective Actions. As a result of a violent exothermic reaction and fire that occured during the splitting of waste stream 92796-1, three employees were injured and one fatality has occured as a result of those injuries. The plant his been damaged. Due to safety and other concerns processing has been restricted. An investigation is under way being performed by an internal team, external agencies, and other contracted experts. Counseling is being provided as requested. Risk Rating: Very High Category:									
VII. Injury Inf	ormation:	<u> </u>			1800				
Name of Injure		Ton Baile	y, John Bed	chak					
Nature of Injur		Burn							
Body Part:		Other							
Work Start Tin	R085076	5:30:00 A							
Employee's Specific Task and Activity at Time of Injury: Tom and John were splitting waste stream number 92796-1. 55 gallon steel drums were overpacked in 85 gallon steel drums under oil. Prior to ermoving the material from the 55s, Tom and John removed the oil using a plastic hand pump. The oil was placed into a lined fiber and solidfied in fiber drums with hand tools and vermiculite. Then, the solid material wasremoved from the inner 55 gallon drum with hand tools and placed in lined fiber drums as well.									
injury Freatme	nt (Click all that	and the second second	eleteral de la faction de la company de la c	FLO Hospital M	est Penn Bum Unit,				
Fatalit Other, Specify		st Aid	Offsite Tre	Pitt, PA	dder dim Bain ding				
			APAN POPULATION AND ADDRESS OF THE P						
Drug and Alco	hol Testing Do	10:	Yes	No	N/A				
Date and Time	in a second seco	12:00:	00 AM	an following the second se					
For Safety N	lanager:								
	29/33								

FEB. 16. 2012 4:43PM

Heritage-WTI, Inc.

NO. 0617 P. 11

First Aid

Recordable

Restricted Duty

Loss Work Days

JAMS

Heritage-WTI, Inc. Incident Report

2011.1539



HERITAGE-WTI, INC. 1250 St. George Street East Liverpool, Ohlo 43920-3400 Phone: 330-385-7337 Fax: 330-385-7813 Web Site: www.heritage-wti.com OHSAS 18001: 2007 ISO 14001: 2004 ISO 9001: 2008

Mr. Scott Nally Ohio Environmental Protection Agency P.O. Box 1049 Columbus, OH 43216-1049 January 13, 2012 CERTIFIED MAIL RETURN RECEIPT REQUESTED

RE:

Unmanifested Waste Report - Rule 3745-54-76 of the Obio Administrative Code

Heritage - WTL, Inc.

USEPA ID No.: OHD 980 613 541 / Ohio Permit no.: 02-15-0589

Dear Mr. Nally:

This letter is being submitted in accordance with rule 3745-54-76 of the Ohio Administrative Code. Rule 3745-547-76 of the Administrative Code requires a facility who accepts for treatment, storage, or disposal any hazardous waste from an off-site source without an accompanying manifest, or without an accompanying shipping paper as described in paragraph. (E)(2) of rule 3745-53-20 of the Administrative Code, and if the waste is not excluded from the manifest requirement by rule 3745-51-05 of the Administrative Code to prepare and submit a single copy of an "Unmanifested Waste Report" to the director within fifteen days after receiving the waste. The specified information is given below.

The EPA Identification number, name, and address of the facility

USBPA I.D. No.:

OHD 980 613 541 Heritage - WTI, Inc. 1250 Saint George Street Bast Liverpool, OH 43920

2. The date the facility received the waste

The waste was received at Heritage – WTI, Inc. on December 13, 2011.

3. The EPA identification number, name, and address of the generator and transporter, if available:

Generator:

USEPA I.D. No.:

ORD 050 955 848

Wah Chang-North

1600 Old Salem Road NE Albany, OR 97321-0460

Transporter #1: USEPA I.D. No.:

KSO 000 336 891

Savannah Transport, Inc. 4425 NW Highway 24 Topeka, KS 66618

4. A description and the quantity of each unmanifested hazardous waste and facility received:

The material was received at the Heritage - WII, Inc. (WII) facility in East Liverpool, OH. The material was shipped as a Flammable Solid on a Uniform Hazardous Waste Manifest without any hazardous waste codes. Specifically, the D.O.T. description did not identify the materials involved as a hazardous waste nor was the shipment carrying hazardous waste codes. WIII received 40 containers on this shipment.

On December 17, 2011, WTI experienced an incident with this material. After the incident, the generator indicated that the material WTI received had a chemical composition of 100% zirconium instead of the 65% zirconium that was listed in the WTI waste stream information. Based on the information from the generator and the incident involving the material, WTI believes this material should carry hazardous waste codes D001 and D003. Specifically, we believe the containers involved in the incident contained waste material that was capable of causing fire through friction, absorption of moisture, or spontaneous chemical changes and when ignited, burned so vigorously and persistently as to create a hazard, Further, we believe that the containers involved in the incident contained materials that were readily capable of detonation or explosive decomposition or reaction at standard temperature and pressure.

We currently are in the process of developing a protocol to safely sample and test the waste to determine whether the remaining containers possess the same physical properties and hazards as the containers involved in the incident.

The method of treatment, storage, or disposal for each hazardous waste:

The waste was and is being managed as a hazardous waste at WTI. WTI reserves the right to reject all or part of the remaining containers of this shipment, and will do so in accordance with OAC 3745-54-72(D). Prior to the incident, WTI had processed six (6) containers of this material. There were two (2) containers involved in the incident, and 32 containers that remain in storage. Until WTI can determine whether the material can be safely rejected to either the original generator or to an alternate facility, the material will remain in a secure location at the WTI facility.

 The certification signed by the owner or operator of the facility or his authorized, representative; and

The certification is provided below.

7. A brief description of why the waste was unmanifested, if known:

Unknown. WTI establishes a waste stream profile for its customers/generators based on wastestream information provided on standardized forms to our personnel. In this instance, the material was identified and shipped as non-hazardous by the generator. After the incident at WTI, the material is believed to be hazardous for D001 and D003.

Please note that the waste material in question was transported in a vehicle which has the appropriate licenses to transport hazardous waste, to a RCRA permitted incinerator, that all parties involved have BPA identification numbers, and the material was designated for and is being managed in hazardous treatment and storage systems at a RCRA-permitted facility.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted.—Based-on-my-inquiry-of-the-person-or-persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are certain penalties for submitting false information including the possibility of fine and imprisonment for knowing violations.

I trust that this information is adequate for your purpose. If there are any questions or comments regarding this matter, please contact me at 330.385.7336.

Sincerely,

Carrie L. Beringer

Environmental, Health, and Safety Manager

Heritage - WII, Inc.

ce: Frank Popotaik – OEPA/DHWM/NEDO Michelle Tarka – OEPA/DHWM/NEDO

ER HOT & HABANERO TOPICS Items of special interest to DEQ EMT, Gov office, legislators, etc:

	Date:_11/15/2011	Name:	Lissa Druback_	
Горіс:	Fire at Envirotech Services Inc.	<u> </u>		

On Thursday, Nov.10, 2011, a fire was reported at Envirotech Services, Inc. in Prineville and the Crook County Fire and Rescue responded to the incident. Envirotech Services makes deicing and dust suppression brines from waste magnesium chloride it receives from Allegheny Technologies, Inc.

The fire started when employees were cleaning up some of their waste materials from the process. This waste contains unoxidized zirconium metal, and the metal created some sparks when the cleaning tool struck the material. The sparks caught some grass on fire which subsequently caught a pallet on fire. The pallet had approximately 8 metal drums of this waste material on it. The drums got quite hot from the fire. DEQ was contacted by CCFR on Monday, Nov. 14, about the incident to better understand the nature of the waste material. Rich Duval, of the HW program, discussed the incident with the Fire Marshall and conducted a site visit on Nov. 15.

DEQ initially became involved in this site because it issued a variance to Allegheny Technologies and Envirotech Services that determined that ATI's waste magnesium chloride was not a hazardous waste when it is used in the Envirotech Services' process. DEQ decided to issue the variance because the waste is treated at ATI in a manner that makes the material similar to raw materials Envirotech had previously purchased from another source. This substance was not involved in the fire.

DEQ also reviewed analytical data and the results of a standard ignitability test on the waste material involved pon request by the Crook County Landfill last summer. DEQ determined that the material is not hazardous, will not ignite on its own without an exterior ignition source, and can be treated as a solid waste and be placed in a landfill. DEQ recommended that Envirotech stabilize the waste prior to disposing of the material so that it would not heat up in the landfill if exposed to an ignition source. Envirotech Services was attempting to do this by mixing the waste with concrete in the drums before disposing of it. However, the process they were using did not fully stabilize the waste.

As a result of the site visit, DEQ will be working with Envirotech Services to develop a better stabilization method for the waste and will recommend better housekeeping methods for their process. DEQ will also provide guidance on proper disposal of the material involved in the fire.

174

Lorah, Steve

"rom:

Davis, Lorraine

∌nt:

Thursday, December 15, 2011 4:05 PM

To:

Lorah, Steve

Subject:

Wah Chang drums from 12/13/11 92796-1

CONFIDENTIAL.

Steve,

I talked with Vince Brown and Eric Feist of Veolia. Vince is the rep that goes on site. He talked to Fred Hamilton at Wah Chang.

According to Vince:

*usually ship in 30 gal drums

*this load was shipped as 55's overpacked into 85's (manifest 000167371VES, 40 drums)

*55's were not DOT shippable, which is why all of them were overpacked, and, could have some rain water contamination in the 55's

*milky look to the oil in the drums is probably a water soluble oil

*the particle size of this load was more finely divided than normal

When I talked to Eric:

*denerator tried to have this material recycled

*this would be why it was in 55's, not 30's originally

*drums sat at recycler for a long time before they decided they couldn't handle them

*drums were in bad condition when they went back to Wah Chang and likely where they were contaminated with rain water (if they actually were)

Let me know if we have to send these back. Do we know how many have already been repackaged?

Lorraine Davis
Customer Coordinator II
Heritage-WTI, Inc.
East Liverpool, OH 43920
330-386-2137 direct / 800-403-4890 toll free
330-386-2167 fax

CONFIDENTIAL

MT ROVA 4/2/2012